PROJECT	I NO. 1115	LANDFIL	L OPERATION TOWN OF P		ORM		
Date	May 15, 2024					TIME 1	:09 PM
	Auditor on si	ite @pen		Close			
PREVIOU	S DATE: Apri	il 24, 2024		Comple	ted		
				- '		E	ast 5 to 10 MPH
WEATHER	Clear,sunny, with clou	ds			V	VIND N	ISEW
TEMP 1	Maximum67	7 °F	Minimum —	67	°F	B.P	29.86
MAJOR E	equipment used in L	andfill of	PERATIONS				
No.	DESCRIPTION	Rented	Contracted	No.	DESCRIPTIO	N Rente	d Contracted
1	Trailer Tipper						
1	Compactor						
2	Dozer						
	Excavator						
	Haul Truck						
	Water Truck						
MAJOR EG	QUIPMENT BONEYARD						
No.	DESCRIPTION	Broken	Maintenance	No.	DESCRIPTIO	N Broker	n Maintenand
Working	Face Size and Locat	ion:					
Working	face in Phase 4b, bringin	a un waste el	evations in the n	hase Tinn	er at lower elev	vation for wa	aste tinning
working		g up nuoto on					
Dozer e	quipped with GPS and per	rforming "desi	gn" work in wast	e placemer	nt		
						-	
					T	YPENW	DOMESTIC
						I DUNY I	RONMENTAL
						2410 N. P.	ALMER STREET EE. WI 53212-3606

	Cover Material:	
	Auto-fluff	
Β.	Leachate Management:	7
	Discharge to Kenosha POTW	
	Two tankers filled on site during aud	it
C.	Gas Monitoring and Manageme	ent: Check appropriate box.
	Flares in Operation: YES	NO 🔳 #
	Engines in Operation: YES 🔳	NO # 8
	Shutdowns Since Last Audit:	# None
	Destructed Volume:	# 2,454 cfm
	Comments:	
	Contractor making connection change	es in cap area.
	No other changes to system	
D	Surface Water Management:	Storm Events Since Last Audit: # 4 Est. Volume ~3"
	-	er road, erosion control structures, erosion damage and possible storm
	Localized flooding about landfill pretty	Ι.
	Basins have plenty of free board, peri	imeter ditches have silt, some cleaning has been done
E.	Odor Control: Odors Present: Onsite	
	Comments:	
	No odors	
F.	Contract Sludge Loads Receive	ed:
	Typical, twice per day	
		Page 2 of

Litter Control:		-		1		1
Litter Present Onsite:		NO				_
Litter Present Offsite:	YES	NO				_
Laborers Active:	YES	NO		# 2		
Comments:						
Laborers picking about	site after pic	king fer	nce li	nes earlier duri	ng the wee	ek
No litter past perimeter	fencina					
	<u></u>					
			mud	/dust, conditio	n of acce	ss and public roads and control measure
taken, instances of trucks	on County I	roads.				
Area roads are clean. S	ite roads are	e rough	at er	ntrance and abo	ut East slo	opes. Remaining site roads relatively smo
Inspection of incomin	<u> </u>	- 1		I	1	1
Scale Camera Operator:	YES 📕	NO		#	1	-
Equipment Operator:	YES	NO		#	3	-
Spotter:	YES	NO NO		#		-
Random Load Inspection Da	ates:	_		5/10/2024		_
Average Tonnage:		52	5 tpc	ł		
Comments:						
MSW, C&D,						
Rejected Loads:						
Date/Time				Re	eason fo	r Rejection
1.						
2.					n	one
					1	
Residential Drop Off	: Open D	ouring	Auc	x tit		
Minimal uses, boxes mos	stly empty ar	id site c	lean			
		L	andf	ill Operations A	udit Form	Page 3

<ul> <li>Gas techs tuning field</li> </ul>		
Auditor's Signature:	Digitally signed by Jo-Walter	Date:
Auditor's Printed Name:	Jo-Walter Spear, Jr. Date: 2024.05.15 14:51:46 -05'00'	Dale.
Management Signature:	Digitally signed by Michael	Date:
	Date: 2024.05.15 15:03:01 -05'00'	Daio
Management Printed Name		
Management Signature: Management Printed Name: Management Title:		Date:
Management litie:		
Management litie:		Doile
Management litie:		Duic



## WMWI – Pheasant Run Landfill LANDFILL CONSTRUCTION AUDIT FORM Town of Paris PROJECT NO. 1115

DATE May 15, 2024

TIME 2:52 PM

#### MAJOR EQUIPMENT USED IN CONSTRUCTION OPERATIONS

No.	DESCRIPTION	Rented	Contracted	No.	DESCRIPTION	Rented	Contracted
	Scrapper						
1	Dozer						
	Excavator						
	Haul Truck						
	Water Truck						
	Sweeper						
1	Compactor						

### A. Work Accomplished Today (Scheduled & Completed):

\* Minimal soil work today, to dry placed clay for next lift. Site has experienced numerous rains this month impacting construction activities

Β.	Excavations	/	Soil	Management:
----	-------------	---	------	-------------

\* Dozer shaping borrow area for clay extraction

#### C. Off Site Hauling

	Weight Ticket Number	Weight of Load in Pounds
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		

Auditor's Signature: Auditor's Printed Name:	Iter Spear, Jr. Date: 2024.05.15 14:58:06 -05'00'	Date:
Management Signature: Management Printed Name:		Date:
Management Printed Name:	Date: 2024.05.15 15:03:26 -05'00'	
Management Title:		

# WMWI PHEASANT RUN LANDFILL / TOWN OF PARIS AUDIT PHOTOS

PROJECT NO. 1155



Waste grades restored and cap being prepared with clay layer





Junction of cap projects



Phase 3 slopes outside of cap project



Waste grades restored and cap being prepared with clay layer



Waste grades restored and cap being prepared with clay layer

AUDIT PHOTOS - 3



Waste grades restored and cap being prepared with clay layer



Waste grades restored and cap being prepared with clay layer



Waste grades restored and cap being prepared with clay layer



Waste grades restored and cap being prepared with clay layer



Previous cap project vegetation covering cap



Previous cap project vegetation covering cap



Active area of Phase 4b



Active area of Phase 4b



Active area of Phase 4b



Active area of Phase 4b



Phase 4; covered until waste placement



Phase 4a

Opened:	09/0/2020		Updated:						
Item Number	DATE month/date/year	Condition Description	Permit or Contract Reference	Initial Schedule for Completion	Observed Completion Date	Elapsed Time (Days)	Notes		